


Ashford Desks Extension Tables User Instructions



Description	Link	8060	BUB	800	1220	1620
Extention Panel	1	1	1	1	1	1
Metal P latte 44 x 66	4	4	2	2	3	4
S crew S PAX ϕ 4x20	24	24	12	12	18	24

SPAX screws can be turned directly into the panels (no drillings are required)